

DOCKET NO: 245841US2



IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF

SIMON RYDER

: EXAMINER: KRAMSKAYA, MARINA

SERIAL NO: 10/722,527

: GROUP ART UNIT: 2858

FILED: NOVEMBER 28, 2003

FOR: A METHOD OF DIAGNOSING A
FAULT ON A TRANSFORMER WINDING

AMENDMENT

COMMISSIONER FOR PATENTS
ALEXANDRIA, VIRGINIA 22313

SIR:

In response to the Office Action dated February 7, 2005, please amend the above-identified application as follows:

Amendments to the Specification begin on page 2 of this paper.

Amendments to the Claims are reflected in the listing of claims which begins on page 3 of this paper.

Remarks begin on page 6 of this paper.